

Department of Environmental Resources		NPDES Compliance Inspection Report										Water Management Program	
Section A: National Data System Coding													
Transaction Code		NPDES				Yr/Mo/Day		Inspection Type		Inspector		Fac Type	
1	N	2	5	3	P	4	A	5	0	6	0	7	0
8	0	9	0	10	0	11	0	12	0	13	0	14	0
15	0	16	0	17	0	18	0	19	0	20	0	21	0
Section B: Facility Data													
Name and Location of Facility Inspected								Entry Time/Date		Permit Effective Date			
CUMBERLAND TWP. AUTH. - SOUTH PLANT								11:00		2-26-92			
RT. 116								Exit Time/Date		Permit Expiration Date			
Municipality								County		2-26-97			
CUMBERLAND TWP.								ADAMS					
Name, Address of Responsible Official								Title					
LAWRENCE J. HELTZEL								AUTH. PRES.					
1370 KANFIELD RD. (C.T.A. BLOC.)								Telephone		Contacted			
GETTYSBURG, PA. 17325								717-334-6485		Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>			
Section C: Areas Evaluated During Inspection													
(S = Satisfactory, I = Improvement Needed, U = Unsatisfactory, D = Does Not Apply, Blank = Not Evaluated)													
___ Permit Verification				___ Flow Measurement				___ Effluent/Receiving Waters					
___ Compliance Schedule				___ Laboratory/QA				___ Operation/Maintenance					
___ Records/Reports				___ Self-Monitoring Program				___ Pretreatment					
___ Other (Specify):													
Section D: Summary of Violations/Recommendations/Comments (Attach additional sheets if necessary)													
VIOLATIONS:													
HYDRAULIC OVERLOAD STATUS AT THIS TIME.													
* FECAL COLIFORM EXCEEDING LIMIT OF 3,500 — 199,000.													
TRACE CHLORINE RESIDUAL DUE TO HIGH FLOW.													
— CALLED L. HELTZEL 3-18-94. FLOW STILL UP —													
.400 ± MGD.													
Inspector Name				Inspector Signature				Title		Date			
DURAND R. LITTLE				DURAND R. LITTLE				WQS		3-8-94			
Name of Person Interviewed				Signature of Person Interviewed				Title		Date			
E. BAKER R. TRIMMER J. KUNKEL				Lawrence J. Helzel				AUTH. PRES.		3-8-94			
L. HELTZEL										717-334-1526			
This document is official notification that a representative of the Pennsylvania Department of Environmental Resources, inspected the above facility. The findings of this inspection are shown above and on any attached pages.													
Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results													